


APPTO.




APPEDE CO., SS SUBCLASS

ATING TIMING FOR IMAGE-CAPTURING (COMPRESSION MODE) SHUTTER RELEASE PRESSED ALL THE WAY DOWN	AF LOCK HOLD AE/AWB	OPERATION READ CHECK DATA TO ACTIVATE READ DOS FAT RECORDING EDIT PHOTOGRAPHIC SYSTEM INFORMATION	OPERATION TO EXPOSE IMAGE READ IMAGE FROM IMAGE ACTIVATE IMAGE —CAPTURING —CAPTURING ELEMENT (REAL —CAPTURING SYSTEM ELEMENT —TIME IMAGE PROCESSING)	OPERATION TO TWO-DIMENSIONAL ACTIVATE IMAGE PROCESSING SYSTEM (TRIAL COMPRESSION) (MAIN COMPRESSION) IMAGE PLANE SIZE CONVERSION FOR DISPLAY PROCESSING TO CREATE THUMBNAIL IMAGE PROCESSING)
OPERATING SHUTTEI DOWN ALL THI	CALCULATE AF/AWB H0	CHECK REMOVABLE MEMORY	TURN OFF POWER OPI TO AE/AF/AWB WITH CHECK DATA RECORDED -C/	AC PR
FIG. 2 SHUTTER RELEASE PRESSED HALFWAY	AE/AF/AWB SYSTEM	RECORDING SYSTEM	IMAGE -CAPTURING SYSTEM	IMAGE PROCESSING SYSTEM









opposest.oetsoo

RAFTSING





, green,
Ē
IJ
C
U
T
Ф
ļ.
•
•
ě

COMPRESSION MODE)	RECORD FILE HEADER	RECORD IMAGE IN REMOVABLE MEMORY	READ IMAGE FROM IMAGE -CAPTURING ELEMENT (REAL -TIME IMAGE PROCESSING)	TWO-DIMENSIONAL IMAGE PROCESSING CONVERSION FOR DISPLAY PROCESSING TO CREATE THUMBNAIL IMAGE THUMBNAIL COMPRESSION (SOFTWARE PROCESSING)
TIMING FOR IMAGE-CAPTURING (NON-COMPRESSION MODE) RELEASE PRESSED WAY DOWN	AF LOCK HOLD AE/AWB	OPERATION READ CHECK DATA TO ACTIVATE READ DOS FAT RECORDING EDIT PHOTOGRAPHIC SYSTEM INFORMATION	OPERATION TO EXPOSE IMAGE ACTIVATE IMAGE —CAPTURING SYSTEM ELEMENT	OPERATION TO ACTIVATE IMAGE PROCESSING SYSTEM
OPERATING SHUTTER DOWN ALL THE	CALCULATE AE/AF/AWB	CHECK REMOVABLE MEMORY	TURN OFF POWER EXCEPT FOR POWER TO AE/AF/AWB WITH CHECK DATA RECORDED	
FIG. 4 SHUTTER RELEASE PRESSED HALFWAY	AE/AF/AWB SYSTEM	RECORD ING SYSTEM	IMAGE -CAPTURING SYSTEM	IMAGE PROCESSING SYSTEM

OPERATING TIMING FOR REPRODUCTION REPRODUCTION MODE ON F1G. 5

-XIN THE CASE OF AN UNCOMPRESSED IMAGE -: IN THE CASE OF COMPRESSED IMAGE REPEAT AND PROCEED TO REPRODUCTION PROCESSING FOR NEXT FRAME IMAGE PLANE SIZE CONVERSION FOR DISPLAY (FOR MONITOR DISPLAY) JPEG DECOMPRESSION READ IMAGE FILE READ DOS FAT AND THE LIKE RETRIEVE MANAGEMENT INFORMATION RELATED TO REPRODUCTION OPERATION TO ACTIVATE REMOVABLE MEMORY REPRODUCTION SYSTEM CONTROL SYSTEM

ogscss...cersoc

DOSOSBEL DELEGO

